

IBILabs

Industrial & Business Intelligence

“Integramos y desarrollamos soluciones digitales y tecnológicas para impulsar su negocio”



Somos una empresa especializada en la adquisición y gestión de información para la supervisión, control y toma de decisiones.


Supervisión e
historización



Control Automático




Proyectos a medida
y equipos especiales




SUPERVISIÓN E HISTORIZACIÓN

En IBILabs atendemos sus requerimientos de supervisión y control (SCADA), e historización de datos de proceso, para el monitoreo y control en tiempo real, y para el análisis de información almacenada. Desde el diagnóstico y diseño conceptual, hasta la implementación y puesta en marcha, incluyendo servicio de mantenimiento 24/7.



139	20HTA10CT003_HL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.5
140	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.7
141	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D297.0
142	20HTA10CT003_Out	179,522	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
143	20HTA10CT003_Sensor_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.2
144	20HTA10CT003_HL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
145	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
146	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
147	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
148	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
149	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
150	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
151	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
152	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
153	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
154	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
155	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
156	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
157	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
158	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
159	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
160	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
161	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
162	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
163	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
164	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
165	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
166	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
167	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
168	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
169	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
170	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
171	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
172	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
173	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
174	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
175	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
176	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
177	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
178	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
179	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
180	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
181	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
182	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
183	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
184	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
185	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
186	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
187	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
188	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
189	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
190	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
191	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
192	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
193	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
194	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
195	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
196	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
197	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
198	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
199	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4
200	20HTA10CT003_LL_Alarm	0	0x80 - good - ok	Binary Tag	1	Line_20	Transmitters	DB100.D296.4



CONTROL & AUTOMATIZACIÓN

¿Su plataforma de control está en riesgo? si su infraestructura tiene más de 15 años o si su proveedor la discontinuó y no consigue soporte, repuestos o si ha estado expuesta permanentemente a condiciones extremas (temperatura, vibraciones, polución, etc.) contáctese con nosotros.


En IBILabs podremos atender su necesidades actuales, incluida la obsolescencia tecnología en comunicaciones, protocolos, estándares, nuevas regulaciones, etc.



PROYECTOS A MEDIDA Y EQUIPOS ESPECIALES

¿Qué es la IoT (internet de las cosas) y como podría beneficiarlo? **¿Necesita una solución personalizada con equipos o sistemas especialmente desarrollados para ud.?** Tenemos la capacidad y experiencia para hacer realidad su proyecto, diseñar e integrar componentes y equipos electrónicos, y aplicar las últimas tecnologías disponibles.

Así mismo podemos medir, transmitir, registrar y analizar la información que ud. requiere y presentársela de la manera, en el momento y en el lugar que la necesite: celular, laptop, paneles LCD de información, etc.



The background features a complex network diagram with numerous circular nodes connected by thin lines. Each node contains a different icon representing various industries and technologies, such as a car, a house, a sun, a battery, a gear, a smartphone, a factory, a satellite, a briefcase, a lightbulb, and a person. A large, semi-transparent circular logo is centered in the middle of the network.

IBILabs

Industrial & Business Intelligence

La Capitanía 80, oficina 108, Las Condes, Santiago
Tel: +56 9 6606 0337
info@ibilabs.cl
www.ibilabs.cl